Release Note

Software Version：2.12.0

Models：i55A/i57A/i505/i505W/i507W/A320i

Date：2025.5.6

Content

Content **2**

1 Revise History **3**

2 Release 2.12.0 ..... **4**

2.1 New Features 4

2.2 Optimization 4

2.3 Bug Fix 4

Fanvil Technology Co., Ltd
Add: 13th Floor, Building 2, Runzhi R D Center, in'an Street, Bao'an District, Shenzhen, Guangdong, China
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

1 Revise History

No.	Version	Release Time
1	2.12.0	2025.5.6

2 Release 2.12.0

Models	Software Version	Comment
i55A	2.12.0.183	
i57A	2.12.0.185	
i505	2.12.0.193	
i505W	2.12.0.187	
i507W	2.12.0.179	
A320i	2.12.0.181	

2.1 New Features

1. Compatible with FCMS, allowing management settings via FCMS to reduce user operations. Works with the Fanvil Link app for remote door opening and monitoring, enhancing user experience.
2. Supports upgrading third-party APK via the web interface.

2.2 Optimization

1. Support configuring monitoring settings through the web interface.
2. Support configuring door unlock settings through the web interface.
3. Support web-based customization of the standby screen, including hide/show options.
4. Added language support for Turkish, Russian, and Korean.
5. Added default alarm tones for security alerts.

2.3 Bug Fix

1. Fixed the issue where IP calls initiated from the contacts list failed.

2. Fixed issues affecting the security alarm functionality.
3. Fixed the problem where some icons on the standby screen were too small to tap.
4. Fixed the bug where changing the incoming call ringtone via the device menu had no effect.
5. Fixed a system crash that could occur when accessing the time settings menu in certain scenarios.
6. Fixed the mismatch between the shortcut key icon and the configured door unlock URL.