

# Release Note

**Software Version：2.12.0**

**Models：A320/A320i/A308**

**Date：2026.6.10**

# Content

**Content** ..... **2**

**1 Revise History** ..... **3**

**2 Release 2.12.0.74x** ..... **4**

2.1 New Features ..... 4

2.2 Bug Fix ..... 4

**3 Release 2.12.0.58x** ..... **5**

3.1 Bug Fix ..... 5

**4 Release 2.12.0.50x** ..... **6**

4.1 New Features ..... 6

4.2 Optimization ..... 6

4.3 Bug Fix ..... 6

**5 Release 2.12.0.44x** ..... **7**

5.1 Bug Fix ..... 7

**6 Release 2.12.0** ..... **8**

6.1 New Features ..... 8

6.2 Bug Fix ..... 8

Fanvil Link Technology Co., Ltd

Add: 13th Floor, Building 2, Runzhi R&D Center, Xin'an Street, Bao'an District, Shenzhen, China.
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

# 1 Revise History

| No. | Version | Release Time |
|---|---|---|
| 1 | 2.12.0 | 2025.9.30 |
| 2 | 2.12.0.44x | 2025.10.31 |
| 3 | 2.12.0.50x | 2026.1.6 |
| 4 | 2.12.0.58x | 2026.2.25 |
| 5 | 2.12.0.74x | 2026.6.10 |
| | | |
| | | |
| | | |

# 2 Release 2.12.0.74x

| Models | Software Version | Comment |
|---|---|---|
| A320 | 2.12.0.741 | |
| A320i | 2.12.0.742 | |
| A308 | 2.12.0.740 | |

## 2.1 New Features

1. Added support for remote device configuration via FCMS.

2. Added support for device diagnostics and device information retrieval via FCMS. interface.

## 2.2 Bug Fix

1. Fixed an issue where manually captured screenshots during calls were cropped and displayed incompletely.

2. Fixed an issue where the custom door unlock button name was not fully displayed on the call screen.

3. Fixed an issue where the device continued ringing after a call was answered through the Fanvil Link App.

4. Fixed an issue where the number on the management station was not updated after the device IP address changed.

5. Fixed an issue where the application could crash when entering the network settings page in certain scenarios.

# 3 Release 2.12.0.58x

| Models | Software Version | Comment |
|---|---|---|
| A320 | 2.12.0.589 | |
| A320i | 2.12.0.590 | |
| A308 | 2.12.0.588 | |

## 3.1 Bug Fix

1. Fixed an issue where contacts, door phone lists, and other data retrieved from FCMS were not displayed completely.

# 4 Release 2.12.0.50x

| Models | Software Version | Comment |
|---|---|---|
| A320 | 2.12.0.507 | |
| A320i | 2.12.0.509 | |
| A308 | 2.12.0.506 | |

## 4.1 New Features

1. Added support for modifying the door unlock password via FCMS, with automatic synchronization to indoor units to enhance system security.
2. Added call forwarding functionality.
3. Added support for customizing the door unlock button during calls.
4. Added support for customizing door unlock and call buttons in the monitoring interface.

## 4.2 Optimization

1. Increased the maximum number of monitoring access channels to 52.

## 4.3 Bug Fix

1. Fixed an issue where setting the system time zone to UTC-3 did not take effect.
2. Fixed an issue where calls could not be placed when dial rules contained alphabetic characters.

# 5 Release 2.12.0.44x

| Models | Software Version | Comment |
|---|---|---|
| A320 | 2.12.0.447 | |
| A320i | 2.12.0.446 | |
| A308 | 2.12.0.448 | |

## 5.1 Bug Fix

1. Fixed an issue where no ringback tone was heard during device calls.

# 6 Release 2.12.0

| Models | Software Version | Comment |
|---|---|---|
| A320 | 2.12.0.426 | |
| A320i | 2.12.0.425 | |
| A308 | 2.12.0.431 | |

## 6.1 New Features

1. Added support for calling indoor station and the APP by entering the room number on the dial interface.

## 6.2 Bug Fix

1. Fixed an issue where audio stuttering and poor sound quality occurred during calls between devices under FCMS.
2. Fixed an issue where switching between monitoring pages was not smooth.