

Release Note

Software Version：2.8.13

Models：i51W/i52W/i53W

Date：2021.6.3

Content

Content **2**

1 Revise History **3**

2 Release 2.8.13 ..... **4**

2.1 New Features 4

2.2 Optimization 4

2.3 Bug Fix 4

2.4 New Features Description 5

1 Revise History

No.	Version	Release Time
1	2.8.13	2021.6.3

2 Release 2.8.13

Models	Software Version	Comment
i51W/i52W/i53W	2.8.13	

2.1 New Features

1. Support preview video when the group is ringing
2. Add hotspot extension management, support group ringing
3. Add Polish
4. Support to adjust volume, mute, enable/disable DND function through standby (i51W & i52W)
5. Add screen calibration function

2.2 Optimization

1. Improve RTSP preview related functions
2. Improve the energy-saving mechanism of device screen savers
3. Improve the date display format in Chinese
4. Improve the SIP video preview function enabled by default
5. Second incoming call support video preview
6. Support IP scan function
7. Improve date display format in Chinese

2.3 Bug Fix

1. Fix the problem of occasional disconnection when connecting to the hot host as a hot client

2. Fix the problem where the device did not respond after frequently opening the door
3. Fix the problem that there is no prompt when the webpage is restored to factory settings when the device is calling
4. Fix the problem that the ‘&’ in the xml file causes the parsing to fail
5. Fix the incoming call not ringing problem caused by the ringtone
6. Fix the issue of Israel's daylight saving time
7. Fix the problem that the webpage cannot export Wi-Fi log
8. Fix the problem that the active URI with non-numeric characters cannot be called
9. Fix the problem that the function does not take effect when the push is muted during a call
10. Fix the problem that the device fails to delete the dynamic list using HTTP API
11. Fix the problem where the time format was set to 12 hours and the time display of memos and call logs did not follow the change
12. Fix the problem that the device does not respond when pressing the unlock key on standby (i51W & i52W)
13. Fix issue with IP camera not being able to preview video when bound to DSSKEY

2.4 New Features Description


1. Support preview video when the group is ringing

Function Description：Door phone calls indoor phone, all indoor phone can ring and display the video of door phone

Select i53W as the hotspot server, other indoor phone and door phone as the client, add indoor phone and access control to a group, set the door machine extension number caller ID video on i53W

2. Add hotspot extension management, support group ringing

Function Description： As a hotspot server, the indoor phone can manage the extension equipment, upgrade, restart, edit the account, set the group and other functions



3. Support to adjust volume, mute, enable/disable DND function through standby (i51W & i52W)

Function Description： When i51W & i52W is on standby, long press the answer button (the fifth button from the left) to enter the function key reuse interface, and you can adjust the volume, mute and enable/disable DND operations