# Release Note

Software Version：2.12.15.8

Models：

V62/V64/V65/X4U-V2/X5U-V2/X6U-V2/X7-V2/X7C-V2/X210-V2/X210i-V2

Date：2022. 12. 16

# Content

**Content** ..... **2**

**1 Revise History** ..... **3**

**2 Release 2.12.15.8** ..... **4**

2.1 Optimization ..... 4

**3 Release 2.12.15.1** ..... **5**

3.1 New Features ..... 5

3.2 Optimization ..... 5

3.3 Bug Fix ..... 6

**4 Release 2.12.X** ..... **7**

4.1 Optimization ..... 7

**5 Release 2.12.2** ..... **8**

5.1 Known Issues ..... 8

# 1 Revise History

| No. | Version | Release Time |
|---|---|---|
| 1 | 2.12.2 | 2022.3.10 |
| 2 | 2.12.X | 2022.8.19 |
| 3 | 2.12.15.1 | 2022.10.11 |
| 4 | 2.12.15.8 | 2022.12.16 |
| | | |
| | | |

# 2 Release 2.12.15.8

| Models | Software Version | Comment |
| --- | --- | --- |
| V62/V64/V65/X4U-V2/X5U-V2/ X6U-V2/X7-V2/X7C-V2/X210-V 2/X210i-V2 | 2.12.15.8 | |

## 2.1 Optimization

1. Optimize the problem of French translation

# 3 Release 2.12.15.1

| Models | Software Version | Comment |
|---|---|---|
| V64/V62/V65/X4U-V2/X5U-V2/ X6U-V2/X7U-V2/X7C-V2/X210-V2/X210i-V2 | 2.12.15.1 | The following X-V2 representative model: X7-V2 / X7C-V2 / X210-V2 / X210i-V2<br><br>The X-V2 representative model: X4U-V2 / X5U-V2 / X6U-V2 |

## 3.1 New Features

1. The X7-V2 / X7C-V2 supports an external CM60 camera.
2. Add Italian.
3. Add the "Mcast Listening Renew Time" feature
4. Support for sending Action URL via SIP info
5. Dial Plan adds a <=> rule that replaces the number before the equal sign and inserts the number after the equal sign
6. Support user custom setting of SIP Call-id fields
7. Support the status of the DND using BLF under a specific server

## 3.2 Optimization

1. Support for modifying the corresponding ringtones for Bellcore-drX
2. Optimize the XU-V2 / X-V2 Series ringtone files
3. Optimize the function of voice message button exhaled

4. Extend LDAP Server field length is 127 bits long
5. Optimize the X-V2 / X-V2 series webpage and LCD display models with the-V2 logo

## 3.3 Bug Fix

1. Repair the problem of exhaled through the hands-free channel, unable to adjust the size of the bell tone
2. Fix the problem of non-responsive transfer failure
3. Repair the VLAN-related issues
4. Fix Alert Info special ringtones do not work on the problem
5. Fix the problem that the Cisco switch cannot access the WEB page under special circumstances
6. Fix the LDAP Contact-related issues
7. Fix the phone hands-free playback voice distortion problem
8. Repair phone access to IPV6 network, web page shows unconnected problem
9. Fix issues that Action URL was unable to report missed incoming calls
10. Repair the configuration XML broswer and reuse the user name and password of the SIP account, causing the URL to not work

# 4 Release 2.12.X

| Models | Software Version | Comment |
|---|---|---|
| V64/V62/X6U-V2 | 2.12.X | |

## 4.1 Optimization

1.Optimize translation issues related to contacts

# 5 Release 2.12.2

| Models | Software Version | Comment |
|---|---|---|
| V62/V64 | 2.12.2 | |

## 5.1 Known Issues

1. In some cases, if you use G723 and G726 codecs to establish a call, the phone may have abnormal faults.