Release Note

Software Version：2.12.18.2

Models：X301W/X303W

Date：2024.4.26

Content

Content **2**

1 Revise History **3**

2 Release 2.12.18.2 ..... **4**

2.1 New Features 4

2.2 New Features Description 4

3 Release 2.12.17.8 ..... **5**

3.1 New Features 5

3.2 Improvement 5

3.3 Bug Fix 5

3.4 New Features Description 6

4 Release 2.12.5.9 ..... **9**

4.1 New Features 9

5 Release 2.12.4.6 ..... **10**

5.1 Optimization 10

5.2 Bug Fix 10

6 Release 2.12.4.2 ..... **11**

6.1 New Features 11

6.2 Optimization 11

6.3 Bug Fix 11

1 Revise History

No.	Version	Release Time
1	2.12.4.2	2023.1.30
2	2.12.4.6	2023.7.28
3	2.12.5.9	2023.8.17
4	2.12.17.8	2024.4.12
5	2.12.18.2	2024.4.26

2 Release 2.12.18.2

Models	Software Version	Comment
X301W/X303W	2.12.18.2	

2.1 New Features

1. Adaptation of key component substitutes and addition of anti degradation function

2.2 New Features Description

This version has added an anti downgrade function. After upgrading to version2.12.18.2, users cannot upgrade to versions lower than 2.12.18.2. The old version in the user's phone can be upgraded to the latest version 2.12.18.2

3 Release 2.12.17.8

Models	Software Version	Comment
X301W/X303W	2.12.17.8	

3.1 New Features

1. Add the function of resetting the web access password
2. Add phone stabilization mechanism
3. Add support for uploading custom languages

3.2 Improvement

1. Optimize issues related to Korean/French translation
2. Optimize RAM to display the actual available memory
3. Optimize the organizational structure of Huawei phonebook
4. Optimize the issue related to automatic update of contacts during auto provisioning
5. Optimize the start and end time of daylight saving time in Israel

3.3 Bug Fix

1. Fix the issue that the configuration items on the web page do not take effect
2. Fix the issue that the user could not enter the LDAP phone book from the softkey
3. Fix the issue that the speed dial key failed to switch channel under special circumstances

4. Fix the issue that the keypad lock would not work after pressing the line key

5. Fix the issue that users failed to add contacts on the LCD


6. Fix the issue that the call timer did not take effect under certain circumstances

3.4 New Features Description

1. Add the function of resetting the web access password

Function description: The phone can reset the web access password separately

Settings: Go to the menu in the phone interface, Menu - Advanced Settings - Factory Reset, and the first item is Web Access. After enabling it, the admin account will be restored to the default password.




2. Add phone stabilization mechanism

Function description: When the device moves or the table vibrates, a new mechanism is added to avoid the situation that the UI interface may change abnormally due to the triggering of the fork spring by the handle

Settings: Enter the phone's website. Find [Phone Settings] - [Media

Settings]-[Onhook Time]. The bigger the number is, the more stable the phone will be.




3. Add support for uploading custom languages

Function description: The phone supports uploading a custom language and displaying it on the screen

Note: Custom language does not work for webpage

Setting: Enter the phone's website. Find [System] - [Upgrade]-[Language Upgrade]. The format and naming is fixed, which is [xstr_list.xst]. If the language is an existing language on the phone, the existing entry content will be replaced. If the language is not supported by the phone, the custom language will be added to the language selection page, and the user can select the custom language to use.


Language Upgrade
Load Server File:
Select
(*.xst)
Upload
Language List
Index
File Name
File Size
x6str_list.xst
225208Bytes
Delete

4 Release 2.12.5.9

Models	Software Version	Comment
X301W	2.12.5.9	

4.1 New Features

1. Add phone screen adaptation, new and old screens share the same software version
2. Add anti degradation function

Description:

This version has added an anti downgrade function. After upgrading to version 2.12.5.9, users cannot upgrade to versions lower than 2.12.5.9. The old version in the user's phone can be upgraded to the latest version 2.12.5.9

5 Release 2.12.4.6

Models	Software Version	Comment
X301W/X303W	2.12.4.6	

5.1 Optimization

1. Optimize high-definition controller related issues.

5.2 Bug Fix

1. Fix the Wi-Fi related issues

6 Release 2.12.4.2

Models	Software Version	Comment
X301W/X303W	2.12.4.2	

6.1 New Features

1. Add G723.1 and G726 codes

6.2 Optimization

1. Optimize the voice quality of the phone

6.3 Bug Fix

1. Fix the French translation display problem