



Release Note

Software Version: 2.14.0.11

Models: H603W

Date: 2025.4.29

Content

- Content 2**
- 1 Revise History 3**
- 2 Release 2.14.0.11 4**
 - 2.1 Optimization 4
 - 2.2 Bug fix 4
- 3 Release 2.14.0.8 5**
 - 3.1 New Features 5
 - 3.2 Bug Fix 5

1 Revise History

No.	Version	Release Time
1	2.14.0.8	2024.11.18
2	2.14.0.11	2025.4.29

2 Release 2.14.0.11

Models	Software Version	Comment
H603W	2.14.0.11	

2.1 Optimization

1. Optimized the voice reminder for controller detachment timeout – press any button to interrupt the announcement.

2.2 Bug fix

1. Fixed audio stutter when pressing number keys in standby mode.

3 Release 2.14.0.8

Models	Software Version	Comment
H603W	2.14.0.8	

3.1 New Features

1. Add voice prompts for enabling and disabling mute.
2. Add a voice prompt feature when the handset exceeds the timeout for being off the base, reminding the user to return it to the base to avoid battery drain, enhancing the user experience.
3. Add automatic answering when the handset is lifted and automatic call hanging up when placed back on the base.

3.2 Bug Fix

1. Fix issues related to Wi-Fi auto deployment.