

Release Note

Software Version：2.12.0

Models：A320/A320i/A308

Date：2025.10.31

Content

Content **2**

1 Revise History **3**

2 Release 2.12.0.44x **4**

2.1 Bug Fix 4

3 Release 2.12.0 ..... **5**

3.1 New Features 5

3.2 Bug Fix 5

Fanvil Link Technology Co., Ltd

Add: 13th Floor, Building 2, Runzhi R&D Center, Xin'an Street, Bao'an District, Shenzhen, China.
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

1 Revise History

No.	Version	Release Time
1	2.12.0	2025.9.30
2	2.12.0.44x	2025.10.31

2 Release 2.12.0.44x

Models	Software Version	Comment
A320	2.12.0.447	
A320i	2.12.0.446	
A308	2.12.0.448	

2.1 Bug Fix

1. Fixed an issue where no ringback tone was heard during device calls.

3 Release 2.12.0

Models	Software Version	Comment
A320	2.12.0.426	
A320i	2.12.0.425	
A308	2.12.0.431	

3.1 New Features

1. Added support for calling indoor station and the APP by entering the room number on the dial interface.

3.2 Bug Fix

1. Fixed an issue where audio stuttering and poor sound quality occurred during calls between devices under FCMS.
2. Fixed an issue where switching between monitoring pages was not smooth.