

Release Note

Software Version：2.12.0

Models：A320/A320i/A308

Date：2026.9.17

Content

Content **2**

1 Revise History **3**

2 Release 2.12.0.90x **4**

2.1 New Features 4

2.2 Optimization 4

2.3 Bug Fix 4

3 Release 2.12.0.74x **5**

3.1 New Features 5

3.2 Bug Fix 5

4 Release 2.12.0.58x **6**

4.1 Bug Fix 6

5 Release 2.12.0.50x **7**

5.1 New Features 7

5.2 Optimization 7

5.3 Bug Fix 7

6 Release 2.12.0.44x **8**

6.1 Bug Fix 8

7 Release 2.12.0 ..... **9**

7.1 New Features 9

7.2 Bug Fix 9

Fanvil Link Technology Co., Ltd

Add: 13th Floor, Building 2, Runzhi R&D Center, Xin'an Street, Bao'an District, Shenzhen, China.
Tel: +86-755-2640-2199 Fax: +86-755-2640-2618 Email: support@fanvil.com www.fanvil.com

1 Revise History

No.	Version	Release Time
1	2.12.0	2025.9.30
2	2.12.0.44x	2025.10.31
3	2.12.0.50x	2026.1.6
4	2.12.0.58x	2026.2.25
5	2.12.0.74x	2026.6.10
6	2.12.0.90x	2026.9.17

2 Release 2.12.0.90x

Models	Software Version	Comment
A320	2.12.0.900	
A320i	2.12.0.901	
A308	2.12.0.899	

2.1 New Features

1. Added support for TLS 1.3.
2. Added support for configuring the device time and date format via FCMS.
3. Added support for configuring the device network mode via FCMS.

2.2 Optimization

1. Added support for customizing alarm prompt tones.
2. Added support for enabling or disabling the add, edit, and delete functions on the Monitoring interface.
3. Improved monitoring display settings to support Single-Window and Multi-Window modes. The default mode is Multi-Window.

2.3 Bug Fix

1. Fixed an issue where video was not displayed during calls with third-party cameras.
2. Fixed browser compatibility issues.

3 Release 2.12.0.74x

Models	Software Version	Comment
A320	2.12.0.741	
A320i	2.12.0.742	
A308	2.12.0.740	

3.1 New Features

1. Added support for remote device configuration via FCMS.

2. Added support for device diagnostics and device information retrieval via FCMS. interface.

3.2 Bug Fix

1. Fixed an issue where manually captured screenshots during calls were cropped and displayed incompletely.

2. Fixed an issue where the custom door unlock button name was not fully displayed on the call screen.

3. Fixed an issue where the device continued ringing after a call was answered through the Fanvil Link App.

4. Fixed an issue where the number on the management station was not updated after the device IP address changed.

5. Fixed an issue where the application could crash when entering the network settings page in certain scenarios.

4 Release 2.12.0.58x

Models	Software Version	Comment
A320	2.12.0.589	
A320i	2.12.0.590	
A308	2.12.0.588	

4.1 Bug Fix

1. Fixed an issue where contacts, door phone lists, and other data retrieved from FCMS were not displayed completely.

5 Release 2.12.0.50x

Models	Software Version	Comment
A320	2.12.0.507	
A320i	2.12.0.509	
A308	2.12.0.506	

5.1 New Features

1. Added support for modifying the door unlock password via FCMS, with automatic synchronization to indoor units to enhance system security.
2. Added call forwarding functionality.
3. Added support for customizing the door unlock button during calls.
4. Added support for customizing door unlock and call buttons in the monitoring interface.

5.2 Optimization

1. Increased the maximum number of monitoring access channels to 52.

5.3 Bug Fix

1. Fixed an issue where setting the system time zone to UTC-3 did not take effect.
2. Fixed an issue where calls could not be placed when dial rules contained alphabetic characters.

6 Release 2.12.0.44x

Models	Software Version	Comment
A320	2.12.0.447	
A320i	2.12.0.446	
A308	2.12.0.448	

6.1 Bug Fix

1. Fixed an issue where no ringback tone was heard during device calls.

7 Release 2.12.0

Models	Software Version	Comment
A320	2.12.0.426	
A320i	2.12.0.425	
A308	2.12.0.431	

7.1 New Features

1. Added support for calling indoor station and the APP by entering the room number on the dial interface.

7.2 Bug Fix

1. Fixed an issue where audio stuttering and poor sound quality occurred during calls between devices under FCMS.
2. Fixed an issue where switching between monitoring pages was not smooth.