



Release Note

Software Version: 1.10.13

Models: X5S/X6/X210

Date: 2019-04-24



1 New Features

1. Support for manually adding Wi-Fi dongle's PID/VID

2 Bug Fixes

1. Fixed the problem where there was no sound when listening to the voice message from the hands-free switch to the handle and adjusting the volume at the same time.
2. Fixed the problem of incorrect LED display when multiple lines are registered and press different dsskey line keys successively in standby mode.
3. Fixed an issue where the time display was incorrect when searching the call log.

3 New Feature Descriptions

1. Support for manually adding Wi-Fi dongle's PID/VID

Description: After successfully adding, you can use this Wi-Fi dongle, enter LCD -> Menu -> Basic -> WLAN, and long press * key to enter the add interface. After setting up, restart to take effect.



The screenshot displays the 'Add Wifi Id' configuration screen. At the top, the title 'Add Wifi Id' is on the left and the time '15:45' is on the right. Below the title, there are three numbered input fields:

- 1. Chip model: Contains the text 'RTL8812' and a small blue icon with '<>' symbols.
- 2. Vendor ID: An empty text input field.
- 3. Product ID: An empty text input field.

At the bottom of the screen, there is a navigation bar with four buttons: 'Return', '123', 'Delete', and 'OK'.